

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jun 30, 2021, 10:39:00 AM

Investigators

Ty

Today's Date

Jun 30, 2021

Time (24Hr)

10:38

Temperature (°F):

86

Rainfall Last 24 hours

Yes

Outfall Photo



field_105-20210630-143839.jpg

Outfall Material

- RCP

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Flared End

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

52

GIS ID

{8F535346-FBE1-418B-B83F-3C5C1E5056DD}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Aug 5, 2021, 3:14:20 PM

Investigators

CC

Today's Date

Aug 5, 2021

Time (24Hr)

15:11

Temperature (°F):

70

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall N

- RCP
- HDPE

Outfall Size

24

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Riprap

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

GIS ID

{2E2AC8E5-B180-4231-ACDC-ED8F65BA7E6A}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Aug 3, 2021, 10:19:02 AM

Investigators

CC

Today's Date

Aug 3, 2021

Time (24Hr)

10:14

Temperature (°F):

69

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **HDPE**

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Flared End

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

404

GIS ID

{1DD98213-7EAD-4649-9EBD-9A283F0C26C0}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Aug 2, 2021, 9:36:26 AM

Investigators

CC

Today's Date

Aug 2, 2021

Time (24Hr)

09:34


Temperature (°F):

70

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall N

- RCP

Outfall Size

24

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

79

GIS ID

{6179F625-21FC-4910-8DA1-7A912C626EEE}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Aug 2, 2021, 9:34:44 AM

Investigators

CC

Today's Date

Aug 2, 2021

Time (24Hr)

09:32

Temperature (°F):

70

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall N

- RCP

Outfall Size

24

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

None

Outfall ID

78

GIS ID

{F318B473-3087-46A8-AD6B-EFC4AF5836AA}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 29, 2021, 10:03:09 AM

Investigators

CC

Today's Date

Jul 29, 2021

Time (24Hr)

09:55


Temperature (°F):

70

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- RCP

Outfall Size

12

Submerged in Water:

Partially

Submerged in Sediment:

Partially

Pipe Condition

- **Clogged with Debris**

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

Pipe clogged. Concerns with flooding in back yard. Extend pipe?

Outfall ID

198

GIS ID

{2D1BCB51-1778-48B9-9296-5A8FC01A2029}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 29, 2021, 9:05:44 AM

Investigators

CC

Today's Date

Jul 29, 2021

Time (24Hr)

09:03

Temperature (°F):

70

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- **CMP**

Outfall Size

18

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

No Outfall Protection

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

403

GIS ID

{9A1660D6-0EB3-45DF-B2F8-8AF900328CD6}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 2:31:30 PM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

14:29

Temperature (°F):

76

Rainfall Last 24 hours

Yes

Outfall Material

- **CMP**

Outfall Size

18

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

No Outfall Protection

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

9999

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 2:31:29 PM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

10:55

Temperature (°F):

70

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall M

- RCP

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Crushed

Outlet Structure

Riprap

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

Fallen trees on pipe

Outfall ID

21

GIS ID

{7CB91D15-FBDC-48D6-934F-16F633C72A96}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 2:31:28 PM

Today's Date

Jul 28, 2021

Time (24Hr)

10:47


Temperature (°F):

70

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall Material

- **CMP**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Corroded (metal)**

Outlet Structure

Headwall

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

20

GIS ID

{9601C33A-6311-42B6-9E9A-ECF4142ECB8D}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 2:31:26 PM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

10:42


Temperature (°F):

70

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall N

- **CMP**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Corroded (metal)**

Outlet Structure

No Outfall Protection

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

19

GIS ID

{832F1A87-E9C7-4FA3-B61C-F19A048682D3}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 2:31:24 PM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

10:15


Temperature (°F):

68

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall M

- RCP

Outfall Size

18

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

Yes

Flow Description

Trickle

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

387

GIS ID

{D50B06FE-0B15-412A-A8E3-4216E4C5B94A}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 10:10:28 AM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

10:09

Temperature (°F):

68

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall N

- RCP

Outfall Size

24

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

116

GIS ID

{57499A16-0184-40F1-A0B2-0C82E2245A57}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 9:55:13 AM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

09:53


Temperature (°F):

68

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall Material

- RCP

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

106

GIS ID

{9C6291B4-E2AE-4456-8CE0-F21BEF448C5F}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 9:39:17 AM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

09:37


Temperature (°F):

66

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall M

- RCP

Outfall Size

18

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

104

GIS ID

{EF41FFB1-C211-4E36-8C28-BE4D2A1998A1}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 9:36:34 AM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

09:35

Temperature (°F):

66

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall Material

- RCP

Outfall Size

18

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

104

GIS ID

{EF41FFB1-C211-4E36-8C28-BE4D2A1998A1}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 9:29:01 AM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

09:26


Temperature (°F):

66

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall N

- RCP

Outfall Size

24

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

103

GIS ID

{349EE3EB-E7F3-47C4-BABA-155A9906BD47}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 28, 2021, 9:18:34 AM

Investigators

CC

Today's Date

Jul 28, 2021

Time (24Hr)

09:14


Temperature (°F):

66

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall M

- **RCP**

Outfall Size

24

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

1 foot of exposed pipe with a hole in it

Outfall ID

102

GIS ID

{97FF5185-7854-4A9B-8817-44F45B12F724}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 27, 2021, 2:58:58 PM

Investigators

CC

Today's Date

Jul 27, 2021

Time (24Hr)

14:52


Temperature (°F):

86

Rainfall Last 24 hours

None

Outfall Photo



Outfall S

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Trickle

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

144

GIS ID

{3139E136-63D2-4351-9414-2F472BAB5536}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 27, 2021, 2:44:29 PM

Investigators

CC

Today's Date

Jul 27, 2021

Time (24Hr)

14:35

Temperature (°F):

86

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- RCP

Outfall Size

12

Submerged in Water:

Fully

Submerged in Sediment:

Partially

Pipe Condition

- Clogged with Debris

Outlet Structure

Flared End

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

356

GIS ID

{D5FE1A18-D68E-457E-A520-0B0B9505912F}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 27, 2021, 9:32:38 AM

Investigators

CC

Today's Date

Jul 27, 2021

Time (24Hr)

09:30

Temperature (°F):

75

Rainfall Last 24 hours

None

Outfall Photo



Outfall ID:

- DI/CI

Outfall Size

24

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Flared End

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

No

Outfall ID

10

GIS ID

{AF272163-0F74-4689-8ACD-01DF9CD8F5CE}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jul 12, 2021, 10:17:04 AM

Investigators

TY

Today's Date

Jul 12, 2021

Time (24Hr)

10:15


Temperature (°F):

66

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall M

- **RCP**

Outfall Size

24

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Headwall

Is Flow Present?

Yes

Flow Description

Trickle

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

Water going into outfall

Outfall ID

116

GIS ID

{57499A16-0184-40F1-A0B2-0C82E2245A57}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: Jun 16, 2021, 10:10:51 AM

Investigators

TY

Today's Date

Jun 16, 2021

Time (24Hr)

10:09


Temperature (°F):

68

Rainfall Last 24 hours

Yes

Outfall Photo



Outfall M

- **HDPE**

Outfall Size

36

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Flared End

Is Flow Present?

Yes

Flow Description

Trickle

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

GIS ID

{5DF2DE7D-40E9-419B-A596-A765CD9671A6}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 2:54:07 PM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

14:51

Temperature (°F):

79

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- **HDPE**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

350

GIS ID

{3309F980-DB22-41C9-898C-E7CACE5D3956}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 2:37:26 PM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

14:35


Temperature (°F):

79

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **CMP**

Outfall Size

24

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**
- **Corroded (metal)**

Outlet Structure

No Outfall Protection

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

43

GIS ID

{C5B40B8E-1558-4F32-BECC-AA6EFA0CC200}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 2:22:12 PM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

14:20

Temperature (°F):

79

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- RCP

Outfall Size

18

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Flared End

Is Flow Present?

Yes

Flow Description

Trickle

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

146

GIS ID

{DAF54E28-8BB4-40FA-AB34-9153289BB690}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 2:04:10 PM .

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

14:03

Temperature (°F):

79

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- RCP

Outfall Size

36

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Flared End

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

133

GIS ID

{98D8877B-A248-4A2C-A9E7-DAC741CE1CD7}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 1:53:44 PM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

13:52

Temperature (°F):

79

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- **CMP**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Corroded (metal)**

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

Very exposed and corroded

Outfall ID

19

GIS ID

{832F1A87-E9C7-4FA3-B61C-F19A048682D3}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 10:22:02 AM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

10:21


Temperature (°F):

63

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- RCP

Outfall Size

36

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

105

GIS ID

{2420C0A9-4A13-4835-8909-CD27149CF78C}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 10:20:31 AM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

10:19

Temperature (°F):

63

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- RCP

Outfall Size

36

Submerged in Water:

Partially

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

104

GIS ID

{EF41FFB1-C211-4E36-8C28-BE4D2A1998A1}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 10:12:09 AM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

10:11

Temperature (°F):

63

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- RCP

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

213

GIS ID

{AC05EE4B-9E51-42C2-85EB-57DDAABEB9C7}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 9:57:46 AM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

09:56

Temperature (°F):

63

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **CMP**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**
- **Corroded (metal)**

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

214

GIS ID

{0D8DC214-8862-4DCD-960D-6FEE61689EB0}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 9:47:17 AM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

09:46

Temperature (°F):

63

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- **PVC**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

96

GIS ID

{6DD5787E-D99D-45C8-96F1-627CA9EEA31F}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 9:36:59 AM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

09:36


Temperature (°F):

63

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **HDPE**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Riprap

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

219

GIS ID

{61FCD54A-787C-46B4-83D3-EF94056041EE}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 21, 2021, 9:23:23 AM

Investigators

TY

Today's Date

May 21, 2021

Time (24Hr)

09:22


Temperature (°F):

63

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- RCP

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Flared End

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

53

GIS ID

{D437DAA6-F183-45F0-B6F6-05EF6931488B}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 20, 2021, 2:39:35 PM

Investigators

TY

Today's Date

May 20, 2021

Time (24Hr)

14:37

Temperature (°F):

70

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **HDPE**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

285

GIS ID

{8A2A249B-3155-4ECC-990E-B48E85C530F2}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 20, 2021, 2:15:25 PM

Investigators

TY

Today's Date

May 20, 2021

Time (24Hr)

14:13

Temperature (°F):

79

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- **CMP**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

195

GIS ID

{5B0992DD-D755-49BD-A18A-37E8DAB76C92}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 20, 2021, 2:03:34 PM

Investigators

TY

Today's Date

May 20, 2021

Time (24Hr)

14:02

Temperature (°F):

79

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **HDPE**

Outfall Size

18

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Headwall

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

23

GIS ID

{8E06633C-3FAD-4543-BDCF-B26C1BAC1DEE}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 2:41:16 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

14:40


Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- HDPE

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

301

GIS ID

{F16C7B3F-00A5-4453-8803-D2D1CCD24BA7}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 2:31:28 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

14:29


Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- RCP

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- Good

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

36

GIS ID

{56879B54-F79F-4D84-B313-7C0F0513BE27}

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 2:22:31 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

14:21


Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- **HDPE**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Flared End

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

Pooling at end of flared end

Outfall ID

2

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 2:13:03 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

14:11

Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- **CMP**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

Partially

Pipe Condition

- **Crushed**

Outlet Structure

No Outfall Protection

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

Seemed like water flows into pipe and it is totally crushed/blocked

Outfall ID

5

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 2:05:45 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

14:04

Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall N

- **CMP**

Outfall Size

18

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Corroded (metal)**
- **Good**

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

9

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 1:53:26 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

13:51

Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **CMP**

Outfall Size

12

Submerged in Water:

Partially

Submerged in Sediment:

Partially

Pipe Condition

- **Good**

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Trickle

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

SECTION 8: Any Non-Illicit Discharge Concerns

Needs to be cleaned out

Outfall ID

320

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 1:35:43 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

13:34

Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall Material

- **CMP**
- **HDPE**

Outfall Size

12

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

328

WilbrahamOutfallInspection

Submitted by: Wilbrahameng

Submitted time: May 19, 2021, 1:29:18 PM

Investigators

TY

Today's Date

May 19, 2021

Time (24Hr)

13:27

Temperature (°F):

81

Rainfall Last 24 hours

None

Outfall Photo



Outfall M

- **RCP**

Outfall Size

15

Submerged in Water:

No

Submerged in Sediment:

No

Pipe Condition

- **Good**

Outlet Structure

Riprap

Is Flow Present?

Yes

Flow Description

Moderate

SECTION 4: Are any Physical Indicators Present in the Flow?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

177

WilbrahamOutfallInspection

Submitted by: SCSwartwout

Submitted time: Jan 28, 2020, 1:36:53 PM

Investigators

Nr

Today's Date

Jul 16, 2019

Time (24Hr)

14:57

Temperature (°F):

90

Rainfall Last 24 hours

None

Outfall Material

- **CMP**

Outfall Size

12

Submerged in Water:

Partially

Submerged in Sediment:

Partially

Pipe Condition

- **Good**

Outlet Structure

Headwall

Is Flow Present?

No

Section 5: Are physical indicators that are not related to flow present?

No

SECTION 6: Overall Outfall Characterization as an Illicit Discharge

Unlikely

Outfall ID

274

GIS ID

{76531591-35BD-48CE-B302-1C0260F38056}

Attachments:




Photo 2.jpg